







-  1. Fastening nut M 8
-  2. Leg M 10 x 50 mm
-  3. Socket cap screw M 8 x 12
-  4. Socket cap screw M 8 x 25
-  5. Socket cap screw M 8 x 30
-  6. Spacer
-  7. Screw connector sleeve M 8
-  8. Fastening plate
-  9. Fastening screw 4 x 25

Note! Two or more persons are needed for assembly.

In demanding environments, we recommend furniture to be fixed to the floor or wall.



Perusosan helat



Jatko-osan helat

